

REFERENCES

- 1-1. Naval Facilities Engineering Command. NAVFAC MO-311: Marine biology operational handbook. Washington, D. C., May 1965.
- 1-2. Naval Facilities Engineering Command. Design manual NAVFAC DM-25: Waterfront operational facilities. Washington, D. C., Oct 1971.
- 1-3. U. S. Department of the Army. Technical Bulletin TB ENG-250: Repair and utilities: Wood preservation. Washington, D.C., Oct 1963.
- 1-4. U. S. Department of the Army. Regulation AR 420-10: Facilities engineering general provisions. Washington, D. C., Oct 1973.
- 1-5. Naval Facilities Engineering Command. NAVFAC MO-322: Inspection guides; structural, mechanical, electrical, vol 2, Washington, D.C., Apr 1971.
- 1-6. U. S. Department of the Air Force. Regulation AFR 85-1: Resources and work force management. Washington, D.C., Apr 1974.
- 1-7. U. S. Department of the Air Force. Manual AFM 86-1: Programming civil engineer resources. Washington, D.C., Sept 1963.
- 1-8. Naval Facilities Engineering Command. Design manual NAVFAC DM-26: Harbor and coastal facilities. Washington, D.C., July 1968.
- 1-9. Naval Facilities Engineering Command. Design manual NAVFAC DM-29: Drydocking facilities. Alexandria, Va, Feb 1974.
- 1-10. U.S. Department of the Army. Technical Manual TM 5-258: Pile construction. Washington, D.C, Jun 1963.
- 1-11. U. S. Department of the Army. Technical Manual TM 5-360: Port construction and rehabilitation. Washington, D.C., Sept 1964.
- 1-12. Army Corps of Engineers. Guide specifications for civil works and for military construction, May 1976.
- 1-13. Federal Construction Council. Federal construction guide specifications. Washington, D.C.
- 1-14. American Association of Port Authorities. Port design and construction. Washington, D.C., 1964. (2d ed. published 1973 under title: Port planning, design and construction).
- 1-15. American Association of Port Authorities. Port maintenance. Washington, D.C., 1970.
- 1-16. Naval Facilities Engineering Command. NAVFAC MO-322: Inspection for Maintenance

Reference-1

of Public Works and Public Utilities, vol. 1, Alexandria, Va, Nov 1974.

1-17. Naval Facilities Engineering Command. NAVFAC MO-124: Mooring maintenance. Alexandria, Va, Dec 1973.

1-18. Naval Facilities Engineering Command. Design manual NAVFAC DM-7: Soil mechanics, foundations and earth structures. Washington, D.C., Mar. 1971.

1-19. U. S. Department of the Army. Technical Manual TM 5-818-1: Engineering and design: Procedures for foundation design of buildings and other structures (except hydraulic structures). Washington, D.C., Aug 1961. (AFM 88-3, chap 7).

1-20. U. S. Department of the Army. Technical Manual TM 5-818-5: Dewatering and groundwater control for deep excavations. Washington, D.C., Apr 1971. (AFM 88-5, chap 6; NAVFAC P-418).

1-21. U. S. Department of the Army. EM 385-1-1: General safety requirements. Washington, D.C, Mar 1967.

1-22. Naval Facilities Engineering Command. NAVFACINST 5100.11A: Command policy and program for safety. Alexandria, Va, July 1971.

1-23. U. S. Department of the Air Force. Manual AFM 127-101: Industrial safety accident prevention handbook, Washington, D.C., June 1970.

2-1. Naval Facilities Engineering Command. AVFAC MO-310: Military entomology operational handbook. Washington, D.C., Dec. 1971.

2-2. Naval Facilities Engineering Command. NAVFAC MO-312: Wood preservation. Washington, D.C., Jan. 1968.

2-3. National Fire Protection Association. Standard 87: Construction and protection of piers and wharves. Boston, Mass., 1971.

2-4. Civil Engineering Laboratory. Techdata Sheet TDS 76-13: Inspection methods for wood fender and bearing piles. Port Hueneme, Calif., Sept 1976.

3-1. Civil Engineering Laboratory. Techdata Sheet TDS 77-02: Epoxy resin for repairing cracked concrete. Port Hueneme, Calif., Jan 1977.

3-2. American Concrete Institute. Committee 506. Shotcreting. Detroit, Mich., 1966. (ACI SP-14)

3-3. ACI Committee 506: "Recommended practice for shotcreting," American Concrete Institute, Journal, Proceedings, vol. 63, no. 2, Feb 1966, pp. 219-246. Discussion. vol 63, no-9, Sept. 1966, pp. 1013-1016.

3-4. American Railway Engineering Association. "Shotcrete," in Manual for railway engineering, chap. 8, pt. 13. Chicago, Ill., 1973, pp. 8-13-1 through 8-13-7.

3-5. NAVFAC Notice 11012 of 9 Jan 1970. Pumping of concrete in aluminum pipe prohibited, Washington, D. C..

3-6. Civil Engineering Laboratory. Technical Report R-271: Epoxy sealers and bonding agents for concrete, by R. L. Alumbaugh, Port Hueneme, Calif., Mar. 1964. (AD 434197)

Reference-2

3-7. ACI Committee 403: "Guide for use of epoxy compounds with concrete," American Concrete Institute, Journal, Proceedings, vol. 59, no. 9, Sept. 1962, pp. 1121-1142. Discussion, vol. 59, Mar. 1963, pt. 2, pp. 2015-2018.

3-8. ACI Committee 504. "Guide to joint sealants for concrete structures, chap. 7. Performance defects, repair, and maintenance of sealants," American Concrete Institute, Journal. Proceedings, vol. 67, no. 7, July 1970, pp. 525-528.

3-9. ACI Committee 515: "Guide for the protection of concrete against chemical attack by means of coatings and other corrosionresistant materials," American Concrete Institute, Journal, Proceedings, vol. 63, no. 12, Dec. 1966, pp. 1305-1392.

4-1. Portland Cement Association. Structural Bureau. Publication ST50. Restoring old stone masonry by pressure grouting, Chicago, 111., 1948.

4-2. D. W. Cole. "Stabilizing constructed masonry dams by means of cement injections" American Society of Civil Engineers, Transactions, vol. 101, 1936, pp. 714-751; discussion, vol. 101, 1936, pp. 752-766.

4-3. H. Hurst. "Pressure grouting damp masonry by the injection of latex-siliconate compositions," Rubber Developments, vol. 21, no. 1, 1968, pp. 37-43.

5-1. Army Engineer Waterways Experiment Station. Miscellaneous Paper H-74-2: Concrete armor units for protection against wave attack, edited by R. Y. Hudson. Vicksburg, Miss., Jan. 1974.

6-1. Naval Facilities Engineering Command. NAVFAC

MO-330: Materials testing. Washington, D. C., Feb 1971.

6-2. TM 5-530 (Army's designation for Reference 6-1).

6-3. AFM 89-3 (Air Force's designation for Reference 6-1).

6-4. American Society for Testing and Materials. Standard D424-59 (Reapproved 1971): Standard method of test for plastic limit and plasticity index of soils. Philadelphia, Pa., 1971.

6-5. American Society for Testing and Materials. Standard D42366 (Reapproved 1972): Standard method of test for liquid limit of soils. Philadelphia, Pa., 1972.

6-6. American Society for Testing and Materials. Standard D42761 (Reapproved 1974). Standard Method of test for shrinkage factors of soils. Philadelphia, Pa., 1974.

6-7. American Society for Testing and Materials. Standard D69858T: Standard Method of test for moisture-density relations of soils using 5.5-lb (2.5-kg) hammer and 12-in. (304.8-mm) drop. Philadelphia, 6-8. 1958. (Superseded by D 698-70) 6-8. American Society for Testing and Materials. Standard D155758T: Standard method of test for moisture-density relations of soils using 10-lb (4.5-kg) hammer and 18-in. (457-mm) drop. Philadelphia, Pa., 1958. (Superseded by D 1557-70)

6-9. U. S. Department of the Army. Technical Manual TM 5-8186: Grouting methods and equipment. Washington, D.C., Feb 1970.

Reference-3

7-1. Naval Facilities Engineering Command. NAVFAC MO-306: Corrosion prevention and control. Washington, D. C., June 1964.

7-2. National Association of Corrosion Engineers. NACE Basic Corrosion Course: Houston, TX, Apr 1971.

7-3. Naval Facilities Engineering Command. NAVFAC MO-110: Paints and protective coatings: Washington, D. C., Jan. 1969. (Joint Service). (Army TM5-618; Air Force AFM85-3).

7-4. J. D. Keane, ed. Steel structures painting manual, vol 2. Systems and specifications, 2d ed. Pittsburgh, Pa., Steel Structures Painting Council, 1964.

7-5. U. S. Department of the Air Force. Manual AFM 88-15: Guidance on surface preparation for painting of steel. Washington, D. C., Jan 1975, Attachment 9.

7-6. Naval Facilities Engineering Command. Type Specification TS 15057: Coal tar coating systems for steel surfaces. Washington, D. C., Apr. 1974.

7-7. R. W. Drisko. "Zinc-rich coatings for marine application," Materials Protection, vol. 9. no. 3, Mar. 1970, pp. 11-12.

7-8. W. D. Parker and W. H. Yeigh. "Petrolatum coated tapes for marine use," Materials Protection and Performance, vol. 11, no. 11, Nov. 1972, pp 31-33.

7-9. C. M. Wakeman, J. W. Storer, and O. E. Liddell. "179 years in sea water?" Materials Protection and Performance, vol. 12, no. 1, Jan. 1973, pp. 14-17.

7-10. R. W. Drisko. "Underwater marine applications of coatings and adhesives," Journal of Paint Technology,

vol. 47, no. 600, Jan. 1975. pp 40-42.

7-11. Naval Facilities Engineering Command. NAVFAC MO-110.1: Facilities engineering management of maintenance painting of facilities. Alexandria, Va, Oct 1973.

7-12. Civil Engineering Laboratory. Techdata Sheet 74-11: Field measurement of paint film thickness. Port Hueneme, Calif., Nov. 1974.

7-13. Naval Facilities Engineering Command. NAVFAC MO-307: Corrosion control by cathodic protection. Washington, D. C., June 1964.

7-14. U. S. Department of the Air Force. Manual AFM 88-9, Chap. 4: Corrosion control. Washington, D.C. Aug 1962.

7-15. Civil Engineering Laboratory. Technical Report R-365: Plastic mooring buoys, pt. 1. Fabrication of experimental models, by R. W. Drisko and T. Roe. Port Hueneme, Calif, Mar 1965 (AD 612055)

7-16. Civil Engineering Laboratory. Technical Report R-750: Urethane foams for Navy pontoon structures, by R. W. Drisko. Port Hueneme, Calif., Nov 1971 (AD 736596)

7-17. Naval Facilities Engineering Command. NAVFAC MO-220: Maintenance and operation of gas systems (triserice). Alexandria, Va, Nov 1970. (AFM 91-6; Army TM 5-654)

7-18. Civil Engineering Laboratory. Techdata Sheet 75-26: Protection of fuel lines under piers. Port Hueneme, Calif., Oct 1975.

Reference-4

7-19. Civil Engineering Laboratory. Techdata Sheet 75-30S: Piping and Conduit for Navy Fuel Piers. Port Hueneme, Calif., Feb 1976.

8-1. S. S. Oleesky and J. G. Mohr. Handbook of reinforced plastics of the society of the plastics industry, Inc., New York, Reinhold, 1964.

8-2. Civil Engineering Laboratory. Techdata Sheet 75-4: Urethane foams for Navy flotation use. Port Hueneme, Calif., Mar 1975.

8-3. Civil Engineering Laboratory. Techdata Sheet 74-12: In-place protection of wooden bearing piles damaged by marine borers Flexible Poly (vinyl chloride)

(PVC) barriers. Port Hueneme, Calif., Dec 1974.

8-4. Civil Engineering Laboratory. Techdata Sheet 75-2: In-place protection of marine borer damaged wooden bearing piles Reinforced mortar filled sleeve barriers. Port Hueneme, Calif., Mar 1975.

8-5. Civil Engineering Laboratory. Techdata Sheet 75-10: Adhesives for use underwater. Port Hueneme, Calif., May 1975.

B-1. Naval Sea Systems Command. Naval ships technical manual, chap. 9190: Preservation of ships in service (paints and cathodic protection). Washington, D.C., Jan 1970. (NAVSEA 0901-LP-190-0002).

Reference-5