

DEPARTMENT OF THE ARMY  
U.S. Army Corps of Engineers  
Washington, DC 20314-1000

CECW-EE

ETL 1110-2-360

Technical Letter  
No. 1110-2-360

31 December 1993

Engineering and Design  
BRAKE WHEEL PROBLEM ON TAINTER GATE HOIST MACHINERY

## **Distribution Restriction Statement**

Approved for public release; distribution is unlimited.